

West Stockwell St

12/87 B

Town Hall Subway

Contractor: Biggs Wall
In charge of works: Ray

30-11-87. Underpinning east side of Town Hall basement. Natural sand at depth of ≈ 2.2 m. from W. Stockwell St. Underpinning is taking place from inside the Town Hall. Basement has removed all archaeological deposits: extends to depth of 4m from street level, is well into natural.

